

XPass 2

Firmware Revision Notes

Version 1.3.2

English

EN 301.00.XP2 V1.3.2

Firmware Version 1.3.2 (Build No. 1.3.2_230116)

Release: 2023-01-26



Devices with the new BLE chip cannot downgrade to a lower version after upgrading the firmware to v1.3.1 or higher. Devices with existing BLE chips can be downgraded to a lower version.

For more information, check the serial number of the device and contact the Suprema (supremainc.com).

New Features and Improvements

1. Separated the log related to the cause of the door unlock.
 - Door open request by exit button
 - Door open request by operator
2. Added relay deactivation option for exit button input.
 - Added the option to set the door open request log to occur but the relay not to operate when the exit button is pressed.

Bug Fixes

1. Card types not checked to be used in smart card settings gets issued normally (Affects version: v1.0.0).
2. Event logs and real-time logs are not output due to corrupted log records (Affects version: v1.0.0).
3. Deleting all users included in an access group in BioStar 2 does not delete the access group from the device's user information (Affects version: v1.0.0).
4. Improved the structure to prevent authentication fail caused by broken database or cache memory (Affects version: v1.0.0).

Firmware Version 1.3.1 (Build No. 1.3.1_220607)

Release: 2022-06-13



Devices with the new BLE chip cannot downgrade to a lower version after upgrading the firmware to v1.3.1 or higher. Devices with existing BLE chips can be downgraded to a lower version.

For more information, check the serial number of the device and contact the Suprema (supremainc.com).

New Features and Improvements

1. Supports setting the byte order for smart cards.
 - Supports setting the byte order of data to be output to Wiegand or OSDP.
2. Supports a new BLE (Bluetooth Low Energy) chip.
 - The BLE chip parts of the hardware have been changed, and the firmware has been upgraded to be compatible with both the existing and new BLE chips.
3. Improved Arm/Disarm state to be written directly to the device's memory so that the state persists even if power is lost.

Bug Fixes

1. The card ID was always output as MSB through OSDP when the card ID is input while the device was connected by an intelligent slave (Affects version: v1.2.3).
2. The user ID was abnormally displayed in the event log if the user authenticated with AoC set as the blacklist card when the User ID Type was set to Alphanumeric (Affects version: v1.0.0).
3. When the device is connected as an intelligent slave and the first card registered to the user is a Wiegand card of a format other than 26-bit, the CSN value is output through OSDP when authenticated with the user's fingerprint (Affects version: v1.2.3).
4. Mobile card authentication suddenly does not work (Affects version: v1.1.0).

Firmware Version 1.2.4 (Build No. 1.2.4_211112)

Release: 2021-11-17



Devices with the new BLE chip cannot downgrade to a lower version after upgrading the firmware to v1.2.4. Devices with existing BLE chips can be downgraded to a lower version.

For more information, check the serial number of the device and contact the Suprema (supremainc.com).

New Features and Improvements

1. Supports a new BLE (Bluetooth Low Energy) chip.
 - The BLE chip parts of the hardware have been changed, and the firmware has been upgraded to be compatible with both the existing and new BLE chips.

Firmware Version 1.2.3 (Build No. 1.2.3_210518)

Release: 2021-05-24

New Features and Improvements

1. Upgraded to the 1.1.1i version of OpenSSL.
2. Intelligent Slave Support
 - Intelligent Slave: A function that enables 1:1 or 1:N matching directly from the Suprema device and transmits the authentication result as OSDP card data to the third-party controller.
3. The transmission power level for Bluetooth Low Energy (BLE) has been adjusted.

Bug Fixes

1. If 31 slave devices were connected and one of the devices got disconnected, the master device rebooted. (Affects version: v1.0.0)
2. Incorrect BitCount was sent if a user authenticated with AoC when the device was connected to a 3rd-party system via OSDP. (Affects version: v1.0.0)
3. When using a static IP while the DNS server address was configured, a reboot on the device caused communication problems between the server and the device. (Affects version: v1.0.0)
4. It failed to reconnect to the slave device after downgrading its firmware version to 1.1.0. (Affects version: v1.0.0)
5. Device responded that it supported transparent mode by OSDP_PDCAP when connecting as a slave while it did not support it. (Affects version: v1.0.0)
6. When calling the BS2_ResetConfigExceptNetInfo API from the BioStar 2 Device SDK, a 'Timeout' error occurred. (Affects version: v1.0.0)
7. The OSDP LED Temporary command did not work properly. (Affects version: v1.0.0)
8. The network reset on the first use was needed to use OSDP default keys to communicate. (for devices released with the firmware version 1.2.0 or later) (Affects version: v1.2.0)
9. It was able to communicate using default keys after changing the key settings when the device was connected to a 3rd-party device via OSDP. (Affects version: v1.0.0)
10. Secure communication was not available by using the default key after downgrading firmware to version 1.1.0 or below which does not support encryption. (Affects version: v1.2.0)

Firmware Version 1.2.2 (Build No. 1.2.2_201006)

Release: 2020-10-15

New Features and Improvements

1. Separated event logs of Mobile Access cards and RFID cards.
2. Support to mobile key deletion when deleting a device data from the Airfob application.

Firmware Version 1.2.1 (Build No. 1.2.1_200612)

Release: 2020-06-26

New Features and Improvements

1. Support encryption for the blacklist and user ID set as an administrator when migrating user information.
2. Improved not to initialize the network and SSL settings when the device ID is changed.

Bug Fixes

1. Issue that the value is not sent to the server since corrupted logs occur.
2. Issue that the connection of the slave device is disconnected when the slave device is connected.
3. Issue that the option for card types is deactivated when the device is connected as a slave after the factory reset.
4. Issue that logs of devices are not sent to the server after the factory reset.

New Features and Improvements

1. Support to the Change Device ID.
2. Enhancement in the security of the device.
 - Restrict unencrypted connections.
 - Support for Secure Tamper on slave devices.
 - Enhancement in the security of encryption keys.
 - Encrypt user information.
 - Restrict access through communications such as TCP/IP, RS-232, and USB.
3. Support for connecting new devices.
 - XPass D2 (Rev 2)
4. Improved Anti-passback zone to operate based on the door status.
5. Support to the BioStar 2 Mobile Access.
6. Support to the Mobile Access V1.1.
7. Support to the scheduled unlock function for each floor when controlling elevator.

Bug Fixes

1. Problem that the password set in the Device Manager app is not initialized even if the factory default is performed.
2. The device does not recognize LF (Low Frequency) cards well.
3. OSDP Communication does not work normally if the value sent to the slave device is greater than the defined value.
4. The Secure Tamper occurs again if a user reboots the device after setting the smart card layout while the Secure Tamper has already occurred.
5. The event log of the device is not sent in the order in which it occurred.

New Features and Improvements

1. Support to the Mobile Credential (NFC, BLE).
2. Added CSN mask for the unknown card type.
 - Before: Cards other than MIFARE, iCLASS, DESFire, iCLASS Seos, FeliCa, ISO-15693 was recognized as CSN.
 - After: User can select whether to recognize cards other than MIFARE, iCLASS, DESFire, iCLASS Seos, FeliCa, and ISO-15693.

Bug Fixes

1. The device recognizes the DESFire(Adv) card as a CSN if the device is restarted when the smart card layout set as DESFire (Adv).
2. The LED indicator operates abnormally when the Device Manager app is disconnected.
3. Changed the color of some of the status lights that previously worked in yellow to green.
4. When using firmware V1.0.1 the connection to the I/O device that using the firmware version below is lost.
 - DM-20 FW V1.1.2
 - OM-120 FW V1.0.0
 - Secure I/O 2 FW V1.2.1
5. The master device intermittently reboots when upgrading the firmware of the slave device.

Firmware Version 1.0.0 (Build No. 1.0.0_190530)

Release: 2019-05-30

Initial firmware developed.



Suprema Inc.

17F Parkview Tower, 248, Jeongjail-ro, Bundang-gu, Seongnam-si, Gyeonggi-do, 13554, Rep. of KOREA
Tel: +82 31 783 4502 | Fax: +82 31 783 4503 | Inquiry: sales_sys@supremainc.com



For more information about Suprema's global branch offices,
visit the webpage below by scanning the QR code.
<https://supremainc.com/en/about/global-office.asp>

© 2023 Suprema Inc. Suprema and identifying product names and numbers herein are registered trade marks of Suprema, Inc.
All non-Suprema brands and product names are trademarks or registered trademarks of their respective companies.
Product appearance, build status and/or specifications are subject to change without notice.