

# BioEntry P2

## Firmware Revision Notes

Version 1.4.1

# Firmware Version 1.4.1 (Build No. 1.4.1\_210511)

Release: 2021-06-01

1. New features and improvements
  - 1.1. Upgraded to the 1.1.1i version of OpenSSL.
  - 1.2. Intelligent Slave Support
    - Intelligent Slave: A function that enables 1:1 or 1:N matching directly from the Suprema device and transmits the authentication result as OSDP card data to the third-party controller.
  - 1.3. Separated event logs of Mobile Access cards and RFID cards.
  
2. Bug Fix
  - 2.1. When calling the BS2\_ResetConfigExceptNetInfo API from the BioStar 2 Device SDK, a 'Timeout' error occurred. (Affects version: v1.0.0)
  - 2.2. Card data were output with the wrong BitCount while the device was communicating with a 3rd party controller via OSDP. (Affects version: v1.0.0)
  - 2.3. When using a static IP while DNS server address was configured, a reboot on the device caused communication problems between the server. (Affects version: v1.0.0)
  - 2.4. While the device was communicating with a 3rd party controller via OSDP, the device connected as a slave responded that it supported transparent mode by OSDP\_PDCAP even though it did not actually support that mode. (Affects version: v1.0.0)
  - 2.5. If 31 slave devices were connected and one of the devices got disconnected, the master device rebooted. (Affects version: v1.0.0)
  - 2.6. Fingerprint authentication did not work after downgrading from firmware version 1.4.0 to firmware version 1.2.1. (Affects version: v1.4.0)
  - 2.7. It was not able to communicate with a 3rd-party controller via OSDP with the default key before network initialization. (only for devices released with the firmware version 1.4.0 or later) (Affects version: v1.4.0)
  - 2.8. It was able to communicate using default keys after changing the key settings when the device was connected to a 3rd-party device via OSDP. (Affects version: v1.3.0)
  - 2.9. After initializing the slave device's settings, it was not able to connect it to a 3rd-party controller. (Affects version: v1.0.0)
  - 2.10. Secure communication was not available by using the default key after downgrading firmware to version 1.3.1 or below which does not support encryption. (Affects version: v1.4.0)

# Firmware Version 1.4.0 (Build No. 1.4.0\_200625)

Release: 2020-07-13

1. New features and improvements
  - 1.1. Added feature to change device ID.
  - 1.2. Enhancement in the security of the device.
    - Restrict unencrypted connections.
    - Enhancement in the security of encryption keys.
    - Encrypt and migrate user information.
  - 1.3. Improved Anti-passback zone to operate based on the door status.
  - 1.4. Improved the scheduled unlock zone function for each floor when controlling elevator.
  - 1.5. Supports new device.
    - XPass D2 (Rev 2)
  - 1.6. Changed the color of LED indicator.
  
2. Bug Fix
  - 2.1. OSDP Communication does not work normally if the value sent to the slave device is greater than the defined value.
  - 2.2. The event log of the device is not sent in the order in which it occurred.
  - 2.3. Issue that the option for card types is deactivated when the device is connected as a slave after the factory reset.
  - 2.4. Issue that the connection of the slave device is disconnected when the slave device is connected.
  - 2.5. Improved the device to recognize unknown cards by selecting the card type options. (BEP2-OA)
  - 2.6. The device reboots or a timeout occurs when upgrading firmware or transferring user data during SSL secure communication.

# Firmware Version 1.3.1 (Build No. 1.3.1\_190911)

Release: 2019-09-19

1. New features and improvements
  - 1.1. Improved the speed at which the device recognizes 13.56 MHz cards.
2. Bug Fix
  - 2.1. The device recognizes the DESFire(Adv) card as a CSN if the device is restarted when the smart card layout set as DESFire(Adv).
  - 2.2. When using firmware V1.3.0 the connection to the I/O device that using the firmware version below is lost.
    - DM-20 FW V1.1.2
    - OM-120 FW V1.0.0
    - Secure I/O 2 FW V1.2.1
  - 2.3. The device restarts if a user authenticates a fingerprint on the device set as below.
    - Byte Order: LSB
    - Wiegand Out: User ID
  - 2.4. After a user scans and registers a card on a device set as Wiegand Out device, if an existing user authenticates with a credential other than the card, the Wiegand output will behave abnormally.
  - 2.5. The master device intermittently reboots when upgrading the firmware of the slave device.

# Firmware Version 1.3.0 (Build No. 1.3.0\_190626)

Release: 2019-07-12

## 1. Important Bug Fix

- 1.1. When a door configured in a Scheduled Unlock Zone is opened by a Scheduled Unlock, the door is not locked if the zone is deleted.
- 1.2. A code is added to prevent the authentication fails because the cache memory is broken.

## 2. New features and improvements

### 2.1. OSDP Standardization

- Improved to comply with OSDP V2.1.7 protocol when connecting with 3rd-party controllers.

### 2.2. Supports Anti-Tailgating.

### 2.3. Supports setting options for Wiegand authentication result output.

- User ID and Card ID

### 2.4. Increase of the number of administrators that can be added.

### 2.5. Increase of the maximum number of floor levels.

### 2.6. Supports options for selection by card type.

### 2.7. Support to the Clear APB for each user.

### 2.8. Supports checking module firmware version.

### 2.9. Supports the latest version of I/O module Micom (V1.3.1).

### 2.10. Firmware upgrade status is added to LED status indicator.

### 2.11. Support for connecting new devices.

- XPass 2(XP2-MDPB, XP2-GDPB, XP2-GKDPB)

## 3. Bug Fix

### 3.1. The device recognizes the iCLASS Seos card as a CSN card.

### 3.2. It does not respond to inputs from the slave device when booting the master device.

### 3.3. Applies FA improvement algorithm.

### 3.4. Start time is not applied in UTC when importing filtered logs using SDK.

### 3.5. A user cannot access BioStar 1.93 when using the latest firmware.

### 3.6. The device cannot recognize iCLASS cards issued by the first generation device.

### 3.7. Supports unsupported devices (FaceStation 2, FaceLite).

### 3.8. HID Prox cards are continuously recognized.

### 3.9. The title of the credential input screen is displayed differently on the master device and the slave device when using multiple authentication mode.

- Existing: master device (user ID, user name), slave device (user ID)

- Update: master device and slave device (user ID, user name)

3.10. Relay works after reconnecting for authentication that occurred when elevator connection is disconnected.

# Firmware Version 1.2.1 (Build No. 1.2.1\_190304)

Release: 2019-03-12

1. Bug Fix
  - 1.1. The device intermittently recognizes the HID Prox card as an EM card.

# Firmware Version 1.2.0 (Build No. 1.2.0\_181119)

Release: 2018-11-29

## 1. Important Bug Fix

- 1.1. When using iCLASS Seos card, the card does not work as set even though the key setting is changed.
- 1.2. A code is added to prevent the authentication fails because the cache memory is broken.

## 2. New features and improvements

- 2.1. Support to the number of users, fingerprints, faces, and cards in Manage Users in Device.
- 2.2. Change the maximum value of the interval and width for the Wiegand Input.
- 2.3. Improves the data protection.
  - Increase the items to encrypt the data.
  - Support to setting the period for storing the personal information.
- 2.4. If the data transmission fails when communicating with OSDP, it is transmitted again.
- 2.5. The site key is initialized if a secure tamper event occurs
- 2.6. If an administrator has registered, modified, or deleted a user, the event log shows whether the editing was done on the server or on the device.
- 2.7. Support to the creation of up to 2048 Access Levels and Access Groups.
- 2.8. Support to AES encryption type for DESFire card.
- 2.9. Support to DESFire/DESFire EV1 Advanced option.
- 2.10. When using The bypass, The card ID is output as Wiegand even though a user authenticates with the AoC.

## 3. Bug Fix

- 3.1. If the user uses the BS\_GetLogBlob command to get the door ID, the door ID is not output normally.
- 3.2. When communicating with OSDP, the LED color is displayed differently from the setting.
- 3.3. The device cannot read CSN because the card recognized as an NFC tag.
- 3.4. Modified the firmware of that slave device so that it cannot be upgraded when a device not supported by the master device is connected as a slave.
- 3.5. If the elevator is configured by connecting the OM-120 to the device, the relays operate differently from the previous status when the slave device is rebooted.
- 3.6. The alarm can be released in the Floors status after a fire alarm occurs when the elevator is configured as a Fire Alarm Zone.

# Firmware Version 1.1.2 (Build No. 1.1.2\_180907)

Release: 2018-09-20

1. New Features and Improvements
  - 1.1. Enhance the solution for the relay processing and restoration.
  
2. Bug Fix
  - 2.1. The device does not recognize the iCLASS card intermittently.
  - 2.2. Modified to exclude an incorrect input when the noise generated in the Wiegand input.

# Firmware Version 1.1.1 (Build No. 1.1.1\_180720)

Release: 2018-07-25

1. New Features and Improvements
  - 1.1. In a device with an LCD, the user name is displayed on the LCD when authentication is successful even when connected in slave mode.
  - 1.2. Support for connecting new devices.
    - XPass D2(XPD2-GDB, XPD2-GKDB)
  
2. Bug Fix
  - 2.1. The bypass does not work when authentication with AoC in Wiegand output.
  - 2.2. Event logs and real-time logs are not uploaded normally to BioStar 2.
  - 2.3. The relay state is not maintained when reconnecting a device connected by RS-485.
  - 2.4. The time zone is not initialized even if the factory reset is performed while secure communication and data encryption key are in use.
  - 2.5. The relay operates according to previous value after reconnection of the device if the authentication is successful when the device set as door relay is disconnected.
  - 2.6. The device restarts when authentication fails.
  - 2.7. The RF module of the device gets damaged when using a 13.56 MHz card.

# Firmware Version 1.1.0 (Build No. 1.1.0\_180317)

Release: 2018-03-26

1. New Features and Improvements
  - 1.1. Support Muster zone.
  - 1.2. Support Reset without Network Settings.
  - 1.3. Support Daylight Saving Time setting.
  - 1.4. Improves Trigger & Action for duress finger.
  - 1.5. Support Private Authentication on AoC.
  - 1.6. Improves to handle the encryption key of the important information stored in database differently from server to server.
  - 1.7. Support One Device Mode(Legacy).
  - 1.8. Added a message asking whether to delete the fingerprint in the database after completing AoC issuance.
  - 1.9. Support the secure tamper.
  - 1.10. Support ISO14443A 10 Byte CSN.
  - 1.11. Support connecting with BioLite N2, XPass D2.
  
2. Bug Fix
  - 2.1. iCLASS 2K card can not be issued as a smart card.
  - 2.2. Problem with reading mobile smart cards on Galaxy S4.
  - 2.3. Galaxy S5 NFC is recognized as a CSN card when authenticating with NFC and the authentication fails.
  - 2.4. Issue that does not work when template size is set to 384 bytes when issuing NFC card.
  - 2.5. Fixed that Hard APB authentication failure notification is distinguished from general authentication failure notification.
  - 2.6. Issue where the device can not read HID Prox II card.
  - 2.7. Fixed to generate buzzer or sound when starting the intrusion alarm.
  - 2.8. Problem that delay time of Action Signal Output is not applied in the slave device.
  - 2.9. Fixed to the device operates in the input waiting state until the authentication time is exceeded when a Wiegand card that is different from the Wiegand format set in the device is input after Arm / Disarm card input.
  - 2.10. Problem where the response rate was slow when Arm / Disarm occurred.
  - 2.11. Fixed to Entrance Limit Soft log to be recorded when authentication exceeds the allowed number.

# Firmware Version 1.0.0 (Build No.1.0.0\_170904)

Release: 2017-09-04

1. Initial firmware developed.



Suprema Inc.  
16F Parkview Tower  
248, Jeongjail-ro, Bundang-gu, Seongnam-si, Gyeonggi-do, 463-863 Republic of Korea  
Tel.+82-31-783-4502 Fax.+82-31-783-4503  
sales@supremainc.com www.supremainc.com